



16 October 2018

Editor  
China Press

**IT IS NOT A REQUIREMENT TO HAVE SPEED LIMIT STICKER FOR FIRE ENGINE VEHICLE INSPECTION**

We refer to the article published on China Press today titled “Speed Limit Sticker Required For PUSPAKOM Inspection”.

PUSPAKOM Sdn Bhd (PUSPAKOM) would like to clarify that it is not a requirement to have a speed limit sticker on the body of fire engine vehicle during its inspection. Under The Road Transport Act 1987, commercial vehicles including fire engine vehicle are required to undergo Routine Inspection at PUSPAKOM every 6 months to ensure it is roadworthy.

At the time of writing, PUSPAKOM has tried to contact the president of the association with relate to the matter but to no avail. We hope the President could contact us on 1-800-88-6927 and we would be more than happy to conduct a briefing for the members of the association to enable them to understand the inspection requirement for fire engine vehicle.

PUSPAKOM wishes to emphasise that we are committed to providing quality and efficient inspection services to our valued customers. PUSPAKOM inspections are to ensure vehicles comply with standards specified by the Road Transport Department (RTD) under the Road Transport Act 1987 and the relevant subsidiary legislations.

PUSPAKOM welcomes feedback from our customers and we always look into any concerns raised by our customers in order to assist and facilitate them to solve any problems faced. For any enquiries or further information, customers can call our Communications & Customer Service Department at 1-800-88-6927 or email to [customerservice@puspakom.com.my](mailto:customerservice@puspakom.com.my).

**COMMUNICATIONS AND CUSTOMER SERVICE DEPARTMENT**

PUSPAKOM Sdn. Bhd.  
03-2052 7465

###